


Index No. A 23

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
N 1/4 1 Corner common to sections 1 AND 36-139-32



EXISTING SURVEYS

Original Government Survey
Year surveyed 1869
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species TAM TAM
Diameter 7" 13"
Bearing S 80° E N 68 1/2° W
Distance 24 LKS 22 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 10-1993 By K. DONAHUE MR/DOT
SPIKE ABOVE 4"x4" CONCRETE MONUMENT
CERT. OF LOCATION DOC. # 408854

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
NAIL & DISK 12" POPLAR N 17° W 76.52
NAIL & DISK FENCE POST S 8° W 38.05
NAIL & DISK FENCE POST S 18° E 38.00
NAIL & DISK FENCE POST S 40° E 44.40

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____