


Index No. R 17-18

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 33 Corner common to sections \_\_\_\_\_



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>ELM</u>	<u>ELM</u>	
<u>5"</u>	<u>7"</u>	
<u>N4W</u>	<u>S68W</u>	
<u>37 LKS.</u>	<u>17 LKS.</u>	

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1936? By CCC

Location filed Washburn Lake - BK # 3 P. 64

Monument 1 P. for MC. 9.6 CH E. of NE 27

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

PLAT - IOWANA HEIGHTS

J.H. FLYNN 1927