


T. 139 R. 26 M. 5th Coordinates: X _____ Y _____

N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search 1908 by Curo
Monument found _____
Surv. Rec. #173, Book A, pg 390

Bearing Trees

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>S 5° E</u>	<u>N 25° E</u>	_____
Distance	<u>11 links</u>	<u>15 links</u>	_____

Original Bearing Trees Found

Species	<u>Norway Pine</u>	_____	_____
Diameter	<u>6"</u>	_____	_____
Bearing	<u>N 25° E</u>	_____	_____
Distance	<u>9.9'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed 4/1908 By J.W. Curo, LS 1428
Location filed: Survey Record #173, Book A, page 390 and Curo
Monument: Set post
Curo Book 95, pages 12 and 30

Evidence of Subsequent Corner Restoration

Year of search 5/1927 By J.P. Larsen, LS 143
Location filed: Plat of TINGDALE BROS.' ROOSEVELT TRAILS
Monument: Concrete Mon.
Document Number 87084.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/2019 By CCHD/SO
Location filed: #2019.006
Monument: Found 1.5" OD iron pipe in concrete
down 0.9', 2'+/-, N. of centerline of trail and witnesses.
18" W. Pine, N 55° E, 46.52' duplex nail, up 1.0', S. side
6" W. Pine, N 44° W, 46.52' duplex nail, up 1.0', E. side
6" N. Pine, S 7° E, 57.07' duplex nail, up 1.0', E. side


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. pine</u>	<u>N. PINE</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>SSE</u>	<u>NRSE</u>	_____
Distance	<u>11 LKS</u>	<u>15 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK "A" P 390-39B
Monument FND 1 ORIG B.T.: 6" N. PINE NRSE 9.9'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

also on microfilm - roll 115 BK 95 P. 12, 31

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - ROOSEVELT TRAILS
J. P. LARSON 1927

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____