Index No. J 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 16 Corner common to sections 9, 10, 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM.	TAM	BIRCH	TAM.
Diameter	5"	6"	6"	6"
Bearing	N 55 E	N 60 W	S 35 E	S 62 E
Distance	5 LKS	13 LKS	14 LKS	43 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - BK# 2 P. 26

Monument Fnd APPROX COR. 3.20 CH. W. of F/line at 74.20 CH from South

1936 - CCC - BK# 7 P. 26 - Fnd 3" Sq Ash 77.81 CH from E

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____