Index No. R 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____

N 1/4 25 Corner common to sections 24, 25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument lost

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	W. CEDAR	W. CEDAR		
Diameter	7"			
Bearing	S10E	N50E		
Distance	9 LKS	5 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1940 By CCC

Location filed Wash burn Lake - BK#4

Monument at 2638 from west - Set temp 1/4 Cor

Fnd old cut line 14' N. - Found all temp cor.

6' W & 14' N. of temp cor

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____