


Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 AND 19, 30-139-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>9"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>N11E</u>	<u>S88W</u>	<u>N77W</u>
Distance	<u>147 LKS</u>	<u>142 LKS</u>	<u>178 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1940 By CCC
Location filed Washburn Lake - BK# 4
Monument at 5276.7' from west - corner is 64' south - also find old temp. sec. cor at 5269' from W. & 45' North of line
1939 - BK# 8 at 5280' from N - set app cor

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1940 By CCC
Washburn Lake - BK# 8
at 5238' from N - set new post approx 92.5' east of line - post in creek w/ yellow tag
15 551E 89.5'

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____