Index No. N19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

N¼ 23 Corner common to sections 14, 23



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM	SPRUCE		
Diameter	8"	6"		
Bearing	N35W	S40E		
Distance	15 LKS	8 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-10"

Monument

1919, BEN CLARK, COUNTY BOOK "C" P.323 FND I.P.
P.337, SET 2½x48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK# 12 P.15
at 2638' from East - Fnd 2" I.P. 20' South of line

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____