Index No. H-5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5th Coordinates: X _____ Y _____

S 1/16 Corner common to sections 7 & 8



EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1975 By W. Curo

Location filed CCSO

Monument Survey indicates mon pipe in place.

Evidence of Subsequent Corner Restoration

Year of search 8/2001 By CCSO

Found 1"/4" ODIP, down 0.5', 2'± W. of ℄ 20th Ave and 15'± S. of ℄ 17th St.

Bearing Trees, Reference Objects

Species	W. Pine	P. Pole	W. Pine	3/4" IP
Diameter	10"		14"	
Bearing	N 52° W	N 50° E	S 56° W	West
Distance	34.72'*	43.20'*	25.19'*	33.0'

*distance to double head nail

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____