Index No. E-F 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 25 M. 5TH Coordinates: X _____ Y _____

MC# 9 Corner common to sections 7,8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1867

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	B. Gilead	W. Cedar
Diameter	6"	8"
Bearing	S 17 E	S 16° W
Distance	28 lks.	76 lks

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1956 By CCC

Location filed Washburn Lake - BK#3 P.70

Monument 33.12 CH N. of E 1/4 7

1956 - DNR - Map on file Corner in place

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____