


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Remonumentation certificate prepared _____

By _____


Filed at _____

Date _____

Index No. E 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 10 Corner common to sections 2, 3, 10, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>W. BIRCH</u>	<u>W. BIRCH</u>	<u>BR. OAK</u>	<u>MAPLE</u>
Diameter	<u>10"</u>	<u>8"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>N31E</u>	<u>S6E</u>	<u>S73W</u>	<u>N88-70W</u>
Distance	<u>12 LKS</u>	<u>20 LKS</u>	<u>16 LKS</u>	<u>33 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK 'A' P 308-312
Monument SET 4x4x36" POST FROM ORIG BIT 5" BR. OAK
S73W 10.6' AND ROOTS OF OTHER 3 BITS.
IN 1911 SET 2 1/2 x 48" I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK#5 P. 46
at 5260 from E. I.P. in road center

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____