


Index No. C5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
Elly 6 Corner common to sections 5, 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Bl. Ash FIR
Diameter 14" 8"
Bearing N30E N60W
Distance 40 LKS. 16 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1941 By CCC
Location filed Washburn Lake - BK# 14 P. 35
Monument at 2640' from South - Set approx 1/4 cor
2" Birch

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____