


Index No. P 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
E1/4 20 Corner common to sections 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>POPULAR</u>	<u>OAK</u>	
Diameter	<u>5"</u>	<u>6"</u>	
Bearing	<u>N82E</u>	<u>S51W</u>	
Distance	<u>19 LKS</u>	<u>40 LKS.</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1965 By R.F. SCHNEIDER
Location filed COUNTY BOOK 'D' P. 459
Monument IRON PIPE - NEW TIES

Evidence of Subsequent Corner Restoration

Year of search 1941 By CCC
Washburn Lake - BK # 15 P. 41
at 2640' from South - set approx cor 3" Birch

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>R. OAK</u>	<u>TWIN BASSWOOD</u>
Diameter	<u>9"</u>	<u>8"</u>	<u>6"</u>
Bearing	<u>N61E</u>	<u>S75E</u>	<u>S31E</u>
Distance	<u>35.9'</u>	<u>8.55'</u>	<u>42.6'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Dec 2002 CCSO
Found 3" ODIP, up 1.0', S1' E. of
E Hunter Lake Trail.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

- * 12" R. Oak N60°E 35.97' up 1.0' N. side
- 10" Birch snag N62°E 25.1' scribed
- 12" R. Oak S72°E 8.94' 8d nail up 1.0' N. side
- 6" Birch S68°W 12.09' 8d nail up 1.3' S side
- * Dist measured to dbl hd. nail

March 1998 Cert of Survey shows
monument found
Mark Aune #22039