


Index No. E 13-14

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
MC # 75 Corner common to sections 3, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>9"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>N9W</u>	<u>S35E</u>	<u>N61E</u>
Distance	<u>7 lks.</u>	<u>19 lks.</u>	<u>8 lks.</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By R. F. Schneider
Location filed _____
Monument Set Iron Pipe

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Trees: 8" Cedar N77E 9.65'
10" W. Pine S16E 10.10'
5" Cedar S32W 14.40'

Copper discs in lower blaze

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____