


Index No. X 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____
C14 Corner common to sections 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEEN - 1978
Doc # 245629
Set 2" x 1/2" galvanized steel pipe with
brass cap. Ties: 7" Tamarack S 26° E 26.70'
6" Tamarack N 20° W 46.40'; 7" Tamarack
S 67° W 61.20'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____