Index No. M 8-9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

W.C. CC Corner common to sections 17

ON 5 1/16 LINE N88°51'W 1.31' FROM 5 1/16 BTW 16,17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919

Original monument 1X36" I.P. W/BRASS CAP CC 517/1919 WC

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species NO TREES WITHIN DISTANCE FOR BITS.

Diameter

Bearing

Distance

Original Bearing Trees Found

Species

Diameter

Bearing

Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species

Diameter

Bearing

Distance

Bearing Trees, Reference Objects

Subsequent Corner Restoration

ear surveyed _____ By _____

ocation filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By Landecker & Assoc.

Cert. of Survey indicates a brass capped monument found.

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____