


Index No. A 6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
w/116 Corner common to sections 5 AND 32-14228



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1921

Original monument 1x36" 1/4" w/ BRASS CAP w/116 532  
55  
1921

Species	Bearing	Trees
<u>ROAK</u>	<u>R 104 R</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>S 15 E</u>	<u>N 41 W</u>	
Distance <u>115 LKS</u>	<u>85 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search 1971 By William Okerman

Set 5 1/2 x 5 1/2 x 24" concrete monument with brass cap.

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>W. Oak</u>	<u>W. Oak</u>	<u>N. Pine</u>
<u>8"</u>	<u>9"</u>	<u>19"</u>
<u>N 56 E</u>	<u>S 17 E</u>	<u>S 9 W</u>
<u>109.10'</u>	<u>143.20'</u>	<u>159.50'</u>

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - BILL OKERMAN - 1971

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_