


Index No. F5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
N 116 Corner common to sections 7, 8



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1x36' I.P. w/brass
CAP

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species MAYLE POPULAR _____
Diameter 9" 14" _____
Bearing S38 3/4 E S35 W _____
Distance 137 LKS 177 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1972 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Oak Oak Oak
7" 5" 7"
S82 E S14 E S45 W
17.50' 30.0' 7.80'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1972

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____