


Index No. G 10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
C.W. 116 Corner common to sections 9



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1 x 3/6" I.P. w/ BRASS CAP C.W. 116 C 59 C
1918

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species J. PINE J. PINE _____
Diameter 6" 12" _____
Bearing N 23 E S 49 1/2 E _____
Distance 25.7 LKS 38.5 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1972 By William Oberman
Found GLO monument in good condition

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Oak J. Pine Birch
5" 5" 7"
S. 28 W N 81 W N 46 E
33.10' 23.00' 15.40'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OBERMAN - 1972

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____