


Index No. K23-24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
W-NE 1/4 Corner common to sections 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P.W. BRASS
CAP

TR
1709
AP3

513
1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Co DITCH SURVEY BK 103 BOX 3 OF
Co DITCH SURVEY BOOKS, PG 26

Evidence of Subsequent Corner Restoration

Year of search 1973 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R. Oak</u>	<u>Maple</u>
<u>11"</u>	<u>9"</u>	<u>10"</u>
<u>N51E</u>	<u>S38E</u>	<u>S74W</u>
<u>9.40'</u>	<u>36.90'</u>	<u>22.60'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1973

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____