


Index No. L-M 22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 28 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC on Corner common to sections 13  
W-N-5 116



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
 Original monument 1x36" I.P. w/ BRASS  
CAP.

513 <sup>W</sup> 513  
<sup>L</sup>  
W  
SMC  
1918

**Bearing Trees**

Species	<u>BL. OAK</u>	<u>J. PINE</u>	_____	_____
Diameter	<u>8"</u>	<u>10"</u>	_____	_____
Bearing	<u>N18E</u>	<u>S74 1/4 W</u>	_____	_____
Distance	<u>120 LKS</u>	<u>51 LKS.</u>	_____	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Plat - Bisbee's Beach - John Howard 1957  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_