


Index No. BC 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SMC ON Corner common to sections 1  
N-S 1/4 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" L.P. W/BASS  
SMC  
51/51  
CAP  
1918  
Species CEDAR CEDAR Trees \_\_\_\_\_  
Diameter 10" 8" \_\_\_\_\_  
Bearing N8 1/4 E S23 1/4 W \_\_\_\_\_  
Distance 30 LKS 70 LKS \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Plat - Spauldins Addition - R.F. Schneider 1970  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_