Index No. F-G 6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections _____

W 1/16 LINE ON N. SHORE OF ISLAND



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/ BRASS CAP

SMC
S8 | S8
W
1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM.	SPRUCE		
Diameter	20"	18"		
Bearing	S1-30E	S37W		
Distance	21 LKS	46 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____