


Index No. 623

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
C14 Corner common to sections 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1836" 1/2" w/BRASS C14 512
CAP 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. PINE W. OAK _____
Diameter 8" 6" _____
Bearing NR2 3/4 E N33 3/4 W _____
Distance 147 LKS 78 LKS _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____