


Index No. J10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
W/16 Corner common to sections 9/16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" i.p. w/BRASS CAP W/16 59 516 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species R. OAK MAPLE
Diameter 14" 10"
Bearing N3-45E S89-30E
Distance 161 LKS 199 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1981 By Gary Stevenson
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

W. OAK W. OAK R. OAK
6" 4" 9"
N39E N65E S72E
33.48' 9.16' 41.94'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260989

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____