

Index No. K-L 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC Corner common to sections 17

ON RE-ESTABLISHED ORIG MONUMENT LINE 28.75 CH. S. OF 1/4 B/W 8:17

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918


Original monument 1x36" 111. W/BASS  
CAP

SMC  
571 517  
C  
1918

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_



○ = Corner

Bearing Trees

Species ROAK ROAK  
Diameter 12" 18"  
Bearing S50-15E SW  
Distance 108 US 201ES

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_