


Index No. 14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
C. E. 11/16 Corner common to sections 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" 1/2 P.W/BARS C E 11/16 C
CAP 5/8 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species R. OAK POPLAR
Diameter 5" 8"
Bearing N69E N87-45W
Distance 57LKS 60LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1963 By Pete Meyer
Found GLO monument in good condition.
5" Red Oak N69E 57 LKS now 17"; 8" Poplar
N87°45'W 60 LKS now 15".

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Red Pine White Pine
10" 15"
N80E S71 1/2 W
78.85' 88.9'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____