


Index No. N 10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
W 1/6 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1x36" 11P. w/GRASS w 1/6 S 1/6
CAD 521
1918

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species OAK MAPLE
Diameter 12" 8"
Bearing WEST N 21 W
Distance 129 LKS 250 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration
Year surveyed 1980 By Gary Stevenson
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species R. Oak R. Oak R. Oak R. Oak
Diameter 10" 9" 8" 8 1/2"
Bearing N 74 W N 2 E S 84 E West
Distance 50.94' 37.14' 73.17' 129 LKS
GLO BT

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 26,1005

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____