


Index No. 75

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E11430 Corner common to sections 29,30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>Poplar</u>	<u>B. Oak</u>	_____	_____
Diameter	<u>6"</u>	<u>7"</u>	_____	_____
Bearing	<u>S47E</u>	<u>N18W</u>	_____	_____
Distance	<u>3 LKS</u>	<u>5 LKS</u>	_____	_____

Original Bearing Trees Found	_____	_____	_____	_____
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 54" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

	Bearing Trees, Reference Objects		
Species	<u>Burr Oak</u>	<u>Maple</u>	<u>Red Oak</u>
Diameter	<u>8"</u>	<u>12"</u>	<u>5"</u>
Bearing	<u>N8W</u>	<u>N82W</u>	<u>N53E</u>
Distance	<u>22.38'</u>	<u>23.22'</u>	<u>46.25'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 31170

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____