


Index No. 29

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SE 32 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>W. Pine</u>	<u>LNW</u>	<u>_____</u>
<u>22"</u>	<u>10"</u>	<u>_____</u>
<u>N50W</u>	<u>N52E</u>	<u>_____</u>
<u>12 LKS</u>	<u>48 LKS</u>	<u>_____</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 2" x 54" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Birch</u>	<u>5"</u>	<u>N31W</u>	<u>45.15'</u>
<u>Maple</u>	<u>6"</u>	<u>N43E</u>	<u>67.02'</u>
<u>N. Pine</u>	<u>24"</u>	<u>N69E</u>	<u>130.17'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - ROTTIERS BABY LAKE NORTH END ADDITION  
MYRON LANDECKER 1974  
PLAT - HOLIDAY SHORES  
MYRON LANDECKER 1975  
1989 Certificate - David Landecker  
Doc. # 311951

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_