


Index No. B19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1x36" I.P. W/BIRCHES N 116° 1' 52" CAP 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POPLAR</u>	<u>R. OAK</u>	
Diameter <u>12"</u>	<u>10"</u>	
Bearing <u>S 30 1/2° E</u>	<u>N 72 1/4° W</u>	
Distance <u>11 LKS</u>	<u>46 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Red Oak</u>	<u>Red Oak</u>	<u>Triple Maple</u>	<u>Red Oak</u>
Diameter	<u>14"</u>	<u>9"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N 72° W</u>	<u>S 62° E</u>	<u>S 30° E</u>	<u>S 48° W</u>
Distance	<u>30.30'</u>	<u>20.10'</u>	<u>33.10'</u>	<u>34.68'</u>

(1917 BT)

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALT Curo - 1981 Doc # 262613