


Index No. 018

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S.W. 1/16 Corner common to sections 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1X36" I.P. W/BRASS SW 1/16 S2  
CAP 1917

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species CEGAR CEGAR \_\_\_\_\_  
Diameter 12" 6" \_\_\_\_\_  
Bearing N44 3/4 E S38 W \_\_\_\_\_  
Distance 25 LKS 23 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species Cedar Cedar Cedar Cedar  
Diameter 8" 8" 6" stump  
Bearing N2W N46W S88W S38W  
Distance 24.50' 20.69' 4.10' 15.5'  
(1917 BT)

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - WALT Curo - 1981  
Doc. #262610

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_