


Index No. P17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1/4 22 Corner common to sections 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	<u>POPULAR</u>	Bearing	<u>R. OAK</u>	Trees	_____
Diameter	<u>12"</u>		<u>10"</u>		_____
Bearing	<u>N63W</u>		<u>N38E</u>		_____
Distance	<u>55 LKS</u>		<u>120 LKS</u>		_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 2" x 48" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>	<u>Red Oak</u>
Diameter	<u>5"</u>	<u>5"</u>	<u>9"</u>
Bearing	<u>S70W</u>	<u>N12E</u>	<u>S12E</u>
Distance	<u>56.72'</u>	<u>35.40'</u>	<u>21.57'</u>

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 311061

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_