


Index No. P9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E14 20 Corner common to sections 20, 21



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Species	Bearing	Tree	Distance
<u>YIPINE</u>	<u>YIPINE</u>		
<u>14"</u>	<u>12"</u>		
<u>S88 1/2 W</u>	<u>S8E</u>		
<u>21 LKS</u>	<u>21 LKS</u>		

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Tree	Distance

Subsequent Corner Restoration
 Year surveyed 1988 By David Landecker
 Location filed _____
 Monument Set 2" x 48" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>Sign Post</u>	<u>Sign Post</u>	<u>Sign Post</u>	
<u>8'</u>	<u>8'</u>	<u>8'</u>	
<u>S60 W</u>	<u>North</u>	<u>S60 E</u>	
<u>6.0'</u>	<u>6.0'</u>	<u>6.0'</u>	

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311059

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____