Index No. H 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

5/16 Corner common to sections 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1X36" I.P. w/BRASS CAP

5/16
5/11 / 5/12
1917

Bearing Trees

Species	CEDAR	CEDAR		
Diameter	10"	10"		
Bearing	S69E	S12¾W		
Distance	207 LKS	281 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Monument Found GLO monument in good condition; 10" Cedar S69E 136.68' now stump; 10" Cedar S 12¾W 185.46' now stump.

Bearing Trees, Reference Objects

Species	Oak	J. Pine	Cedar Post	
Diameter	8"	5"	4x4x72"	
Bearing	S25E	S50½W	North	
Distance	82.6'	121.0'	2.0'	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____