


Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 14 R. 31 M. 5TH Coordinates: X _____ Y _____

E 1/4 17 Corner common to sections 16, 17

WITNESS POST 1 CH. SOUTH



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees	
Species <u>TAm.</u>	<u>TAm.</u>
Diameter <u>10"</u>	<u>10"</u>
Bearing <u>S50E</u>	<u>S8E</u>
Distance <u>545</u>	<u>2345</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1992 By Terry L. Freeman
 Location filed _____
 Monument Found 2" capped iron pipe

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects			
Species <u>Black Spruce</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Tamarack</u>
Diameter <u>7"</u>	<u>20"</u>	<u>5"</u>	<u>stump</u>
Bearing <u>S65W</u>	<u>S10W</u>	<u>S25E</u>	<u>S50E</u>
Distance <u>30.68'</u>	<u>81.00'</u>	<u>21.52'</u>	<u>3.3'</u>

(original)

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1992 Certificate - Terry L. Freeman
Doc. # 343556

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____