


Index No. V 23

CASS COUNTY LAND CORNER RECORD



141 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25, 36

EXISTING SURVEYS

Original Government Survey
 Year surveyed _____
 Original monument _____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1921 By E. B. Horst
 Location filed COUNTY RESURVEY PLAT "E-53"
 Monument Iron Monument
1915, JOHN GURD, COUNTY RESURVEY PLAT "E-56" 2 1/2 x 4 1/2 in
1920, E. B. HORST, BOOK "E" P. 64 FWD I.I.M.
also on microfilm - roll 105 BK 63 P. 55

Evidence of Subsequent Corner Restoration
 Year of search Jan 2003 By C.C.S.O
Found 1 1/4" ODIP, down 0.4 in lawn

Bearing Trees, Reference Objects
 Species 1920 - also on microfilm - roll 115 BK 60 P. 116
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>ODIP</u>
<u>6"</u>	<u>10"</u>	<u>18"</u>	<u>3 1/4"</u>
<u>N 35° W</u>	<u>N 85° E</u>	<u>S 15° W</u>	<u>N 37° W</u>
<u>30.37</u>	<u>29.24</u>	<u>3.30'</u>	<u>14.62</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____