


Index No. G 13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 9 Corner common to sections 9, 10



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>TAM.</u>	<u>BIRM GILEAD</u>
Diameter	<u>10"</u>	<u>14"</u>
Bearing	<u>WEST</u>	<u>N 63 E</u>
Distance	<u>13 LKS</u>	<u>24 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____