Index No. R 21

# CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 26 Corner common to sections 23, 24, 25, 26




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1871

Original monument POST

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | SPRUCE | SPRUCE | SPRUCE | CEDAR |
| Diameter | 6" | 6" | 10" | 8" |
| Bearing | N75W | S33½W | S5E | N82E |
| Distance | 12 LKS | 18 LKS | 13 LKS | 14 LKS |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____