


Index No. 613

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
E14 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey
Year surveyed 1872
Original monument Bst

Original Evidence Found
Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>TAM.</u>	<u>MAPLE</u>
Diameter	<u>8"</u>	<u>4"</u>
Bearing	<u>N89W</u>	<u>S24E</u>
Distance	<u>22 LKS</u>	<u>25 LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1986 By Walt Cyro
Set corner on fence line @ intersection
w/pond and swamp calls. 2"x60" galv. l.f.
w/ brass cap in 24" of water

Bearing Trees, Reference Objects		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects		
<u>Birch</u>	<u>Maple</u>	<u>Maple</u>
<u>10"</u>	<u>6"</u>	<u>6"</u>
<u>N89E</u>	<u>S62°E</u>	<u>S5E</u>
<u>65.38'</u>	<u>34.16'</u>	<u>17.42'</u>

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
Certificate - Walt Cyro 1986
Doc. # 296927

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____