


Index No. G 25

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 57A Coordinates: X _____ Y _____
E 1/4 12 Corner common to sections 12 + 7-142-25



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1871
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees
<u>CEDAR</u>	<u>CEDAR</u>	
Diameter <u>10"</u>	<u>3"</u>	
Bearing <u>S 24 E</u>	<u>N 14 W</u>	
Distance <u>10 LKS</u>	<u>14 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1996, 04 By Laverne Lewelling
Set brass capped galvanized steel pipe at the
"lost" position between the Witness Corner to NE
Corner of Sec. 24 and NE Corner of Sec. 1.
Cert. Filed Dec. 8, 1997; Doc. #395049

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Cedar	Cedar	Triple Cedar
<u>0.250</u>	<u>0.250m</u>	<u>0.180m</u>
<u>N 15 W</u>	<u>N 28 W</u>	<u>S 16 W</u>
<u>25.029m</u>	<u>31.173m</u>	<u>28.173m</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____