


Index No. N 21-22

CASS COUNTY LAND CORNER RECORD

T. 14R R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 11 Corner common to sections 13, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species N. Pine  
Diameter 10"  
Bearing N43W  
Distance 11LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1997, June By Laverne Leuelling  
Set brass capped galvanized steel pipe on  
line between NW & NE corners of Sec. 24 & at  
record G.L.O. distance from NW corner of  
Sec. 24.  
Cert. Filed: Dec 8, 1997; Doc. #395064

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Maple Cedar Maple S. Signpost  
0.127m 0.150m 0.178m  
N16E S11W S76E W  
1.919m 1.080m 5.957m 1.000m

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_