


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees
Species	<u>BIRCH</u>	<u>SPRUCE TAM.</u>
Diameter	<u>10"</u>	<u>6"</u>
Bearing	<u>S4W</u>	<u>S3E</u>
Distance	<u>21.05 CH.</u>	<u>21.00 CH. 931 LKS</u>

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1921 By C.J. White  
 Location filed USFS Notes  
 Monument 2774.6 from 1/4 corner  
✓ 500 LINE MAP

Evidence of Subsequent Corner Restoration

Year of search 1963 By W. Okerman  
Chained from West Falls in road alongside ditch

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

V-9

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_