Index No. F-G 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____

MC # 18 Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species NO. BIT.

Diameter

Bearing

Distance

Original Bearing Trees Found

Species

Diameter

Bearing

Distance

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Location filed SEC. OF STATE

Monument NO OR16. EVIDENCE - (PROPORTIONAL POINT IN RIVER) SET 8' CEDAR POST 6" SQUARE 4' IN GROUND MARKED: MC ON S. SIDE, S 8 ON W. SIDE, T142N R27W ON N. SIDE, S9 ON E. SIDE

Bearing Trees, Reference Objects

Species

Diameter

Bearing

Distance

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____