


Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 12 Corner common to sections 112



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1874  
Original monument POST

Species	Bearing	Trees
<u>MAPLE</u>	<u>MAPLE</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>S10W</u>	<u>N 77E</u>	
Distance <u>22 LKS</u>	<u>13 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1920 By GLO  
Location filed SEC OF STATE  
Monument NO ORIG. EVIDENCE SET 1x36" I.P.W./BRASS  
CAP.  
1/4 51  
512  
1920

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	Bearing	Reference Objects
<u>MAPLE</u>	<u>MAPLE</u>	
Diameter <u>12"</u>	<u>7"</u>	
Bearing <u>N37E</u>	<u>S82-5W</u>	
Distance <u>65 LKS</u>	<u>42 LKS</u>	

**Bearing Trees, Reference Objects**

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_