


Index No. 0-P22

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC ON Corner common to sections 24

W116 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919

Original monument 1X36" I.P. W/BRASS

CAP

Species BALSAM Bearing BALSAM Trees \_\_\_\_\_

Diameter 4" 8" \_\_\_\_\_

Bearing S50-15E S73W \_\_\_\_\_

Distance 15LKS 29LKS \_\_\_\_\_

SMC  
W  
524 T 524  
W  
1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_