


Index No. V 12

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/16 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1928  
Original monument 1x36" I.P.W. BRASS E 1/16 528  
CAP 533

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>OAK</u>	<u>POPLAR</u>	_____	_____
Diameter	<u>5"</u>	<u>3"</u>	_____	_____
Bearing	<u>N 21-15E</u>	<u>S 68-15E</u>	_____	_____
Distance	<u>96 LKS</u>	<u>106 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_