


Index No. Y-23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections 31
N-S 1/4 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
 Original monument 1X36" I.P. W/BOYSS
 Species OAK Bearing OAK Trees _____
 Diameter 15" 18"
 Bearing N53E N17-15W
 Distance 49LKS 35LKS

SMC
531 531
1918

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Plat - Rogers Peninsula
- Gary Stevenson 1981

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____