


Index No. 11-N-11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 54 Coordinates: X _____ Y _____

164 Corner common to sections 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
 Original monument 1" x 36" l.P. w/ Bar. Cap TR 1360 TP 1411 #23

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1964 By Pete Meyer
 Location filed _____
 Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Red Pine Oak
 Diameter 22" 10"
 Bearing S 74 W S 9 1/2 W
 Distance 63.0' 56.15'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1964

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____