


Index No. N 15-16

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MCH# 7 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_ *Same as*  
Original monument \_\_\_\_\_ *1/4 corner*

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed \_\_\_\_\_  
Monument 1" x 36" I.P. w/ Br. Cap - no  
evidence of original.

Evidence of Subsequent Corner Restoration

Year of search 1965 By William Okerman  
Found GLO monument in good condition.  
6" Oak S64W 11.22' now 12"  
5" Oak N76W 13.20' now 12"

Bearing Trees, Reference Objects

Species Oak Oak  
Diameter 6 5  
Bearing S64W N76W  
Distance 17 lks 20 lks

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1965

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_