


Index No. R-4

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E. 1/16 Corner common to sections 19:30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1" x 3/16" I.P. w/ Br. Cap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. Oak R. Oak  
Diameter 4 7  
Bearing N68E S55 1/2 E  
Distance 75 lks 14 lks

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species R. Oak Cedar Post  
Diameter 6" 4x4x72"  
Bearing S53E West  
Distance 8.70' 2.00'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1971  
Plat - 1st Addition to Heathman Estates - R.E. Schneider  
1977

Reinonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_